


55.

Explanation of how to read wiring diagrams



P4A004101

Reference key

- A Component number
- B Connection number
- C Identification of connector at component
- D Connecting pin number
- E Ultrasound welding taped in cable loom

4A0041